

in accordance with HSNO

Revision: 25.09.2023 Printing date 28.09.2023 Version number 9

1 Identification of the substance or mixture and of the supplier

· Product identifier

· Trade name: Mipa Vicrom "mirror glaze"

· Relevant identified uses of the substance or mixture and uses advised against

No further relevant information available.

· Application of the substance / the mixture Paint

· Details of the supplier of the safety data sheet

· Manufacturer/Supplier:

MIPA SE

Am Oberen Moos 1 D-84051 Essenbach Tel.: +49 8703 92 20 Fax.: +49 8703 92 21 00

e-mail: sdb-registratur@mipa-paints.com

www.mipa-paints.com

· Emergency telephone number: International emergency number: +49(0)700 24112112 (MIP)

Importer in New Zealand:

RJP Performance Coatings 33 Ha Crescent, Wiri Auckland 2104 Phone: 09 25000 91 Email: sales@mipa.nz

24HR Emergency Assistance in New Zealand: National Poison Control Centre: 0800 POISON [764 766]

Web: www.mipa.nz

2 Hazards identification

· Classification of the substance or mixture



Flam. Liq. 3 H226 Flammable liquid and vapour.



health hazard

STOT RE 2 H373 May cause damage to organs through prolonged or repeated exposure.

Asp. Tox. 1 H304 May be fatal if swallowed and enters airways.



Skin Irrit. 2 H315 Causes skin irritation.

Eye Irrit. 2 H319 Causes serious eye irritation.

STOT SE 3 H336 May cause drowsiness or dizziness.

- · Label elements
- · GHS label elements

The product is classified and labelled according to the Globally Harmonised System (GHS).

Hazard pictograms







GHS02 GHS07

· Signal word Danger

· Hazard-determining components of labelling:

Xylene

n-Butyl acetate

2-Methoxy-1-methylethyl acetate

Ethylbenzene

(Contd. on page 2)



in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 1)

· Hazard statements

H226 Flammable liquid and vapour.

H315 Causes skin irritation.

H319 Causes serious eye irritation.

H336 May cause drowsiness or dizziness.

H373 May cause damage to organs through prolonged or repeated exposure.

H304 May be fatal if swallowed and enters airways.

Precautionary statements

P101 If medical advice is needed, have product container or label at hand.

P102 Keep out of reach of children.

P103 Read carefully and follow all instructions.

P301+P310 IF SWALLOWED: Immediately call a POISON CENTER/ doctor.

P321 Specific treatment (see on this label).

P331 Do NOT induce vomiting.

P303+P361+P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin

with water [or shower].

P305+P351+P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact

lenses, if present and easy to do. Continue rinsing.

P362+P364 Take off contaminated clothing and wash it before reuse.

P501 Dispose of contents/container in accordance with local/regional/national/

international regulations.

· Other hazards

· Results of PBT and vPvB assessment

· **PBT:** Not applicable. · **vPvB:** Not applicable.

3 Composition/Information on ingredients

- · Chemical characterisation: Mixtures
- · **Description:** Mixture of substances listed below with nonhazardous additions.

· Dangerou	s components:	
123-86-4	n-Butyl acetate	25-50%
	🚸 Flam. Liq. 3, H226; 仆 STOT SE 3, H336	
108-65-6	2-Methoxy-1-methylethyl acetate	25-50%
	🚸 Flam. Liq. 3, H226; 🐠 STOT SE 3, H336	
1330-20-7		10-25%
	♦ Flam. Liq. 3, H226; ♦ STOT RE 2, H373; Asp. Tox. 1, H304; ♦ Acute Tox. 4, H312; Acute Tox. 4, H332; Skin Irrit. 2, H315; Eye Irrit. 2, H319	
78-93-3	Methyl ethyl ketone	10-25%
	🊸 Flam. Liq. 2, H225; 🕩 Eye Irrit. 2, H319; STOT SE 3, H336	
100-41-4	Ethylbenzene	2.5-<10%
	♦ Flam. Liq. 2, H225; ♦ STOT RE 2, H373; Asp. Tox. 1, H304; ♦ Acute Tox. 4, H332; Skin Irrit. 2, H315; Eye Irrit. 2, H319; Aquatic Chronic 3, H412	
108-21-4	isopropyl acetate	<2.5%
	♦ Flam. Liq. 2, H225; ♦ Eye Irrit. 2, H319; STOT SE 3, H336	
141-78-6	Ethyl acetate	<2.5%
	🊸 Flam. Liq. 2, H225; 🕦 Eye Irrit. 2, H319; STOT SE 3, H336	
	₩ 1 Id. 1. 2, 11220, ₩ 2. 1010, 0101 02 0, 11000	

· Additional information: For the wording of the listed hazard phrases refer to section 16.

4 First aid measures

- · General information: Immediately remove any clothing soiled by the product.
- · After inhalation: Supply fresh air; consult doctor in case of complaints.

(Contd. on page 3)



in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 2)

· After skin contact: Immediately rinse with water.

· After eve contact:

Rinse opened eye for several minutes under running water. If symptoms persist, consult a doctor.

- After swallowing: Seek immediate medical advice.
- · Information for doctor:
- · Most important symptoms and effects, both acute and delayed

No further relevant information available.

· Indication of any immediate medical attention and special treatment needed

No further relevant information available.

5 Fire fighting measures

· Suitable extinguishing agents:

CO2, powder or water spray. Fight larger fires with water spray or alcohol resistant foam.

- · For safety reasons unsuitable extinguishing agents: Water with full jet
- · Special hazards arising from the substance or mixture

During heating or in case of fire poisonous gases are produced.

· Protective equipment: Mouth respiratory protective device.

6 Accidental release measures

· Personal precautions, protective equipment and emergency procedures

Mount respiratory protective device.

Wear protective equipment. Keep unprotected persons away.

- Environmental precautions: Do not allow to enter sewers/ surface or ground water.
- · Methods and material for containment and cleaning up:

Absorb with liquid-binding material (sand, diatomite, acid binders, universal binders, sawdust).

Dispose contaminated material as waste according to section 13.

Ensure adequate ventilation.

Reference to other sections

See Section 7 for information on safe handling.

See Section 8 for information on personal protection equipment.

See Section 13 for disposal information.

7 Handling and storage

- · Handling:
- · Precautions for safe handling

Ensure good ventilation/exhaustion at the workplace.

Prevent formation of aerosols.

· Information about fire - and explosion protection:

Keep ignition sources away - Do not smoke.

Protect against electrostatic charges.

Keep respiratory protective device available.

- · Storage:
- · Requirements to be met by storerooms and receptacles: No special requirements.
- Information about storage in one common storage facility: Store away from foodstuffs.
- · Further information about storage conditions: Keep container tightly sealed.
- · Storage class: 3
- · Specific end use(s) No further relevant information available.

NZ ·



Safety Data Sheet in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 3)

•	ols/personal protection			
	tion about design of technical facilities: No further data; see section 7.			
Ingredients with limit values that require monitoring at the workplace:				
123-86-4 n-Butyl ac				
WES (New Zealand)	Short-term value: 950 mg/m³, 200 ppm			
1051.V (511)	Long-term value: 713 mg/m³, 150 ppm			
OELV (EU)	Short-term value: 723 mg/m³, 150 ppm Long-term value: 241 mg/m³, 50 ppm			
108-65-6 2-Methoxy	v-1-methylethyl acetate			
OELV (EU)	Short-term value: 550 mg/m³, 100 ppm			
	Long-term value: 275 mg/m³, 50 ppm Skin			
1330-20-7 Xylene				
WES (New Zealand)	Long-term value: 217 mg/m³, 50 ppm oto			
OELV (EU)	Short-term value: 442 mg/m³, 100 ppm			
	Long-term value: 221 mg/m³, 50 ppm Skin			
78-93-3 Methyl ethy	/l ketone			
NES (New Zealand)	Short-term value: 890 mg/m³, 300 ppm			
	Long-term value: 445 mg/m³, 150 ppm bio			
OELV (EU)	Short-term value: 900 mg/m³, 300 ppm			
	Long-term value: 600 mg/m³, 200 ppm			
100-41-4 Ethylbenz				
WES (New Zealand)	Short-term value: 176 mg/m³, 40 ppm Long-term value: 88 mg/m³, 20 ppm			
	skin, oto			
OELV (EU)	Short-term value: 884 mg/m³, 200 ppm			
, ,	Long-term value: 442 mg/m³, 100 ppm			
	Skin			
108-21-4 isopropyl				
WES (New Zealand)	Short-term value: 1290 mg/m³, 310 ppm Long-term value: 1040 mg/m³, 250 ppm			
141-78-6 Ethyl acet				
WES (New Zealand)	Long-term value: 720 mg/m³, 200 ppm			
OELV (EU)	Short-term value: 1468 mg/m³, 400 ppm Long-term value: 734 mg/m³, 200 ppm			
	, , , , , , , , , , , , , , , , , , ,			

- · Additional information: The lists valid during the making were used as basis.
- · Personal protective equipment:
- General protective and hygienic measures:

Keep away from foodstuffs, beverages and feed.

Immediately remove all soiled and contaminated clothing

Wash hands before breaks and at the end of work.

Store protective clothing separately.

Avoid contact with the eyes.

Avoid contact with the eyes and skin.

(Contd. on page 5)



in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 4)

· Respiratory protection:



In case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure use self-contained respiratory protective device.

Protection of hands:

Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation



Protective gloves (EN 374)

The glove material has to be impermeable and resistant to the product/ the substance/ the preparation.

Material of gloves

The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance of the glove material can not be calculated in advance and has therefore to be checked prior to the application.

· Breakthrough time of glove material

The exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.

Eye protection:



Tightly sealed goggles

9 Physical and chemical properties

· General Information

· Appearance:

· Form: Fluid

· Colour: According to product specification

Odour: Characteristic
 Odour threshold: Not determined.
 pH-value: Not determined.

· Change in condition

· Melting point/freezing point: Undetermined. · Initial boiling point and boiling range: 79-80.5 °C

Flash point: 24 °C (DIN EN ISO 1523:2002)

Flammability (solid, gas): Flammable.

• Auto-ignition temperature: 315 °C (DIN 51794)
• Decomposition temperature: Not determined.

· **Ignition temperature:** Product is not selfigniting.

• Explosive properties: Product is not explosive. However, formation of explosive

air/vapour mixtures are possible.

· Explosion limits:

Lower: 1.1 Vol %
 Upper: 11.5 Vol %
 Vapour pressure at 20 °C: 105 hPa
 Vapour pressure at 50 °C: 55 hPa

Density at 20 °C: 0.892 g/cm³ (DIN EN ISO 2811-1)

(Contd. on page 6)



in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 5)

Relative density
 Vapour density
 Evaporation rate
 Not determined.
 Not determined.

· Solubility in / Miscibility with

· water: Not miscible or difficult to mix.

· Partition coefficient: n-octanol/water: Not determined.

· Viscosity:

Dynamic: Not determined.Kinematic at 20 °C: 10-12 s (DIN 53211/4)

· Solvent content:

• **VOC (EC)** 99.55 %
• **Solids content (weight-%):** 0.5 %

· Other information No further relevant information available.

10 Stability and reactivity

- · Reactivity No further relevant information available.
- Thermal decomposition / conditions to be avoided: No decomposition if used according to specifications.
- · Possibility of hazardous reactions No dangerous reactions known.
- Conditions to avoid No further relevant information available.
- · Incompatible materials: No further relevant information available.
- Hazardous decomposition products: Carbon monoxide

11 Toxicological information

- · Information on toxicological effects
- · Acute toxicity Based on available data, the classification criteria are not met.
- · Skin corrosion/irritation Causes skin irritation.
- · Serious eye damage/irritation Causes serious eye irritation.
- Respiratory or skin sensitisation Based on available data, the classification criteria are not met.
- Germ cell mutagenicity Based on available data, the classification criteria are not met.
- · Carcinogenicity Based on available data, the classification criteria are not met.
- · Reproductive toxicity Based on available data, the classification criteria are not met.
- · STOT-single exposure May cause drowsiness or dizziness.
- STOT-repeated exposure May cause damage to organs through prolonged or repeated exposure.
- · Aspiration hazard May be fatal if swallowed and enters airways.

12 Ecological information

- · Toxicity
- · Aquatic toxicity: No further relevant information available.
- · Persistence and degradability No further relevant information available.
- · Behaviour in environmental systems:
- · Bioaccumulative potential No further relevant information available.
- · Mobility in soil No further relevant information available.
- Additional ecological information:
- · General notes:

Water hazard class 2 (German Regulation): hazardous for water

Do not allow product to reach ground water, water course or sewage system.

Danger to drinking water if even small quantities leak into the ground.

(Contd. on page 7)



in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 6)

- · Results of PBT and vPvB assessment
- · PBT: Not applicable.
- · vPvB: Not applicable.
- Other adverse effects No further relevant information available.

13 Disposal considerations

- · Waste treatment methods
- · Recommendation

Must not be disposed together with household garbage. Do not allow product to reach sewage system.

- Uncleaned packaging:
- · Recommendation: Disposal must be made according to official regulations.

	-	4		
14	ıranç	nort	Into	rmation
	ruis	9016	тто	madon

· NZS, IMDG, IATA UN1263

· UN proper shipping name

NZS UN1263 PAINT

· **IMDG, IATA** PAINT

· Transport hazard class(es)

· NZS



· Class 3 (F1) Flammable liquids.

· Label

· IMDG, IATA



· Class 3 Flammable liquids.

· Label 3

· Packing group

· NZS, IMDG, IATA ///

· Environmental hazards:

· Marine pollutant: No

· Special precautions for user Warning: Flammable liquids.

· Hazard identification number (Kemler code): 30

· EMS Number: F-E,S-E

· Stowage Category A

· Transport in bulk according to Annex II of

Marpol and the IBC Code Not applicable.

(Contd. on page 8)



in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

	(Contd. of page
Transport/Additional information:	
NZS	
Limited quantities (LQ)	5L
Transport category	3
Tunnel restriction code	D/E
IMDG	
Limited quantities (LQ)	5L
UN "Model Regulation":	UN 1263 PAINT, 3, III

15 Regulatory information

· Safety, health and environmental regulations/legislation specific for the substance or mixture

· HSNO App	· HSNO Approval numbers		
	n-Butyl acetate	HSR001091	
1330-20-7	Xylene	HSR000983	
78-93-3	Methyl ethyl ketone	HSR001190	
100-41-4	Ethylbenzene	HSR001151	
	isopropyl acetate	HSR001182	
141-78-6	Ethyl acetate	HSR001041	

· GHS label elements

The product is classified and labelled according to the Globally Harmonised System (GHS).

· Hazard pictograms







GHS02 GHS07 GHS08

- · Signal word Danger
- · Hazard-determining components of labelling:

Xylene

n-Butyl acetate

2-Methoxy-1-methylethyl acetate

Ethylbenzene

· Hazard statements

H226 Flammable liquid and vapour.

H315 Causes skin irritation.

H319 Causes serious eye irritation.

H336 May cause drowsiness or dizziness.

H373 May cause damage to organs through prolonged or repeated exposure.

H304 May be fatal if swallowed and enters airways.

Precautionary statements

P101 If medical advice is needed, have product container or label at hand.

P102 Keep out of reach of children.

P103 Read carefully and follow all instructions.

P301+P310 IF SWALLOWED: Immediately call a POISON CENTER/ doctor.

P321 Specific treatment (see on this label).

P331 Do NOT induce vomiting.

(Contd. on page 9)



in accordance with HSNO

Printing date 28.09.2023 Version number 9 Revision: 25.09.2023

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 8)

P303+P361+P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin

with water [or shower].

P305+P351+P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact

lenses, if present and easy to do. Continue rinsing.

P362+P364 Take off contaminated clothing and wash it before reuse.

P501 Dispose of contents/container in accordance with local/regional/national/

international regulations.

· Directive 2012/18/EU

· Named dangerous substances - ANNEX I None of the ingredients is listed.

· Seveso category P5c FLAMMABLE LIQUIDS

Qualifying quantity (tonnes) for the application of lower-tier requirements 5,000 t

Qualifying quantity (tonnes) for the application of upper-tier requirements 50,000 t

· National regulations:

· Additional classification according to Decree on Hazardous Materials, Annex II:

Class	Share in %
NK	50-100

· Other regulations, limitations and prohibitive regulations

Surface Coatings and Colourants (Flammable) Group Standard 2006

HSNO Approval Number: The HSNO Approval Number for this Group Standard is HSR002662.

Refer also to the Site & Storage requirements document.

· Chemical safety assessment: A Chemical Safety Assessment has not been carried out.

16 Other information

This information is based on our present knowledge. However, this shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship.

Relevant phrases

H225 Highly flammable liquid and vapour.

H226 Flammable liquid and vapour.

H304 May be fatal if swallowed and enters airways.

H312 Harmful in contact with skin.

H315 Causes skin irritation.

H319 Causes serious eye irritation.

H332 Harmful if inhaled.

H336 May cause drowsiness or dizziness.

H373 May cause damage to organs through prolonged or repeated exposure.

H412 Harmful to aquatic life with long lasting effects.

· Contact:

Abbreviations and acronyms:

ADR: Accord relatif au transport international des marchandises dangereuses par route (European Agreement Concerning the International Carriage of Dangerous Goods by Road)

IMDG: International Maritime Code for Dangerous Goods

IATA: International Air Transport Association

EINECS: European Inventory of Existing Commercial Chemical Substances

ELINCS: European List of Notified Chemical Substances

CAS: Chemical Abstracts Service (division of the American Chemical Society)

VOC: Volatile Organic Compounds (USA, EU)

PBT: Persistent, Bioaccumulative and Toxic

vPvB: very Persistent and very Bioaccumulative

Flam. Liq. 2: Flammable liquids - Category 2

Flam. Liq. 3: Flammable liquids - Category 3

Acute Tox. 4: Acute toxicity - Category 4

Skin Irrit. 2: Skin corrosion/irritation - Category 2

Eye Irrit. 2: Serious eye damage/eye irritation – Category 2

STOT SE 3: Specific target organ toxicity (single exposure) – Category 3 STOT RE 2: Specific target organ toxicity (repeated exposure) – Category 2

Asp. Tox. 1: Aspiration hazard - Category 1

(Contd. on page 10)





Safety Data Sheet in accordance with HSNO

Revision: 25.09.2023 Printing date 28.09.2023 Version number 9

Trade name: Mipa Vicrom "mirror glaze"

(Contd. of page 9)

Aquatic Chronic 3: Hazardous to the aquatic environment - long-term aquatic hazard — Category 3 \cdot * Data compared to the previous version altered.