

Printing date 28.09.2023

Safety Data Sheet

in accordance with HSNO Version number 4

Revision: 22.09.2023

1 Identification of the substance or mixture and of the supplier

· Product identifier

· Trade name: Mipa 2K-Express-Beschleuniger

• **Relevant identified uses of the substance or mixture and uses advised against** No further relevant information available.

· Application of the substance / the mixture Accelerator

• Details of the supplier of the safety data sheet

Manufacturer/Supplier:

MIPA SE Am Oberen Moos 1 D-84051 Essenbach Tel.: +49 8703 92 20 Fax.: +49 8703 92 21 00 e-mail: sdb-registratur@mipa-paints.com Importer in New Zealand: RJP Performance Coatings

33 Ha Crescent, Wiri Auckland 2104 Phone: 09 25000 91 Email: sales@mipa.nz Web: www.mipa.nz

24HR Emergency Assistance in New Zealand:

www.mipa-paints.com

National Poison Control Centre: 0800 POISON [764 766]

Emergency telephone number: International emergency number: +49(0)700 24112112 (MIP)

2 Hazards identification

· Classification of the substance or mixture



Flam. Liq. 2 H225 Highly flammable liquid and vapour.

health hazard

STOT RE 2 H373 May cause damage to the lung through prolonged or repeated exposure. Route of exposure: Inhalation.



Eye Irrit. 2 H319 Causes serious eye irritation. STOT SE 3 H336 May cause drowsiness or dizziness.

· Label elements

· GHS label elements

The product is classified and labelled according to the Globally Harmonised System (GHS). • Hazard pictograms



· Signal word Danger

• *Hazard-determining components of labelling: n-Butyl acetate Benzoic acid Ethyl acetate*

Hazard statements
H225 Highly flammable liquid and vapour.
H319 Causes serious eye irritation.

(Contd. on page 2)

NZ

Printing date 28.09.2023

Safety Data Sheet

in accordance with HSNO

Version number 4

Revision: 22.09.2023

Trade name: Mipa 2K-Express-Beschleuniger

	(Contd. of page 1)
H336 May caus	se drowsiness or dizziness.
-	se damage to the lung through prolonged or repeated exposure. Route of exposure:
• Precautionary	statements
P210	Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
P260	Do not breathe dust/fume/gas/mist/vapours/spray.
P280	Wear protective gloves/protective clothing/eye protection/face protection/hearing protection.
P303+P361+P3	353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].
P304+P340	IF INHALED: Remove person to fresh air and keep comfortable for breathing.
	338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
Other hazards	
· Results of PB	T and vPvB assessment
• PBT: Not applie	

· **vPvB:** Not applicable.

3 Composition/Information on ingredients

[•] Chemical characterisation: Mixtures

· Description: Mixture of substances listed below with nonhazardous additions.

· Dangerous components:		
123-86-4	n-Butyl acetate	50-100%
	🚸 Flam. Liq. 3, H226; 🚸 STOT SE 3, H336	
141-78-6	Ethyl acetate	25-50%
	🚸 Flam. Liq. 2, H225; 🚸 Eye Irrit. 2, H319; STOT SE 3, H336	
	Benzoic acid	≥1-<2.5%
	🚸 STOT RE 1, H372; 🔶 Eye Dam. 1, H318; 🚸 Skin Irrit. 2, H315	
Additional information: For the wording of the listed hazard phrases refer to section 16.		

4 First aid measures

· General information: Immediately remove any clothing soiled by the product.

• After inhalation: Supply fresh air; consult doctor in case of complaints.

· After skin contact: Immediately rinse with water.

• After eye contact:

Rinse opened eye for several minutes under running water. If symptoms persist, consult a doctor. • **After swallowing:** If symptoms persist consult doctor.

Information for doctor:

• *Most important symptoms and effects, both acute and delayed* No further relevant information available.

• *Indication of any immediate medical attention and special treatment needed* No further relevant information available.

5 Fire fighting measures

[.] Suitable extinguishing agents:

CO2, powder or water spray. Fight larger fires with water spray or alcohol resistant foam.

For safety reasons unsuitable extinguishing agents: Water with full jet

• Special hazards arising from the substance or mixture

During heating or in case of fire poisonous gases are produced.

(Contd. on page 3)

NZ

Safety Data Sheet

in accordance with HSNO

Version number 4

Revision: 22.09.2023

Trade name: Mipa 2K-Express-Beschleuniger

· Protective equipment: Mouth respiratory protective device.

6 Accidental release measures

- · Personal precautions, protective equipment and emergency procedures Mount respiratory protective device.
- Wear protective equipment. Keep unprotected persons away.
- Environmental precautions: Do not allow to enter sewers/ surface or ground water.
- Methods and material for containment and cleaning up: Absorb with liquid-binding material (sand, diatomite, acid binders, universal binders, sawdust). Dispose contaminated material as waste according to section 13.
- Ensure adequate ventilation. Reference to other sections See Section 7 for information on safe handling. See Section 8 for information on personal protection equipment. See Section 13 for disposal information.

7 Handling and storage

· Handling:

- · Precautions for safe handling Keep away from heat and direct sunlight. Ensure good ventilation/exhaustion at the workplace. Prevent formation of aerosols.
- · Information about fire and explosion protection: Keep ignition sources away - Do not smoke. Protect against electrostatic charges. Keep respiratory protective device available.
- · Storage:
- · Requirements to be met by storerooms and receptacles: Store in a cool location.
- · Information about storage in one common storage facility: Store away from foodstuffs.
- · Further information about storage conditions:
- Keep container tightly sealed. Store in cool, dry conditions in well sealed receptacles.
- · Storage class: 3
- · Specific end use(s) No further relevant information available.

8 Exposure controls/personal protection

· Additional information about design of technical facilities: No further data; see section 7.

· Ingredients with limit values that require monitoring at the workplace:

123-86-4 n-Butyl acetate		
WES (New Zealand)	Short-term value: 950 mg/m³, 200 ppm Long-term value: 713 mg/m³, 150 ppm	
IOELV (EU)	Short-term value: 723 mg/m³, 150 ppm Long-term value: 241 mg/m³, 50 ppm	
141-78-6 Ethyl acetate		
WES (New Zealand)	Long-term value: 720 mg/m³, 200 ppm	
IOELV (EU)	Short-term value: 1468 mg/m³, 400 ppm Long-term value: 734 mg/m³, 200 ppm	
• Additional information: The lists valid during the making were used as basis.		

(Contd. on page 4) NZ

(Contd. of page 2)

Safety Data Sheet

in accordance with HSNO Version number 4

Revision: 22.09.2023

Printing date 28.09.2023

Trade name: Mipa 2K-Express-Beschleuniger

(Contd. of page 3)

- · Personal protective equipment:
- General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Immediately remove all soiled and contaminated clothing Wash hands before breaks and at the end of work. Store protective clothing separately. Avoid contact with the eyes. Avoid contact with the eyes and skin.
- Respiratory protection:



In case of brief exposure or low pollution use respiratory filter device. In case of intensive or longer exposure use self-contained respiratory protective device.

· Protection of hands:

Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation



Protective gloves (EN 374)

The glove material has to be impermeable and resistant to the product/ the substance/ the preparation.

· Material of gloves

The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation of several substances, the resistance of the glove material can not be calculated in advance and has therefore to be checked prior to the application.

Breakthrough time of glove material

The exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.

Fluid

Characteristic

Not determined.

• Eye protection:



Tightly sealed goggles

9 Physical and chemical properties

· General Information

- · Appearance:
- · Form:
- · Colour:
- · Odour:
- · Odour threshold:
- · pH-value:
- Change in condition
- Melting point/freezing point: Undetermined
- · Initial boiling point and boiling range: 77-78 °C
- · Flash point:
- Flammability (solid, gas):
- Auto-ignition temperature:
- Decomposition temperature:

Not determined. Undetermined. 77-78 °C -4 °C (DIN EN ISO 1523:2002)

According to product specification

- Highly flammable. 370 °C (DIN 51794)
 - Not determined.

(Contd. on page 5)

NZ



Safety Data Sheet

in accordance with HSNO

Revision: 22.09.2023

Printing date 28.09.2023

Version number 4

Trade name: Mipa 2K-Express-Beschleuniger

	(Contd. of page 4)
· Ignition temperature:	Product is not selfigniting.
Explosive properties:	Product is not explosive. However, formation of explosive
	air/vapour mixtures are possible.
• Explosion limits:	
· Lower:	1.2 Vol %
· Upper:	11.5 Vol %
Vapour pressure at 20 °C:	97 hPa
Vapour pressure at 50 °C:	360 hPa
Density at 20 °C:	0.894 g/cm ³ (DIN EN ISO 2811-1)
· Relative density	Not determined.
· Vapour density	Not determined.
• Evaporation rate	Not determined.
Solubility in / Miscibility with	
water:	Not miscible or difficult to mix.
· Partition coefficient: n-octanol/water:	Not determined.
· Viscosity:	
· Dynamic:	Not determined.
· Kinematic:	Not determined.
· Solvent content:	
· VOC (EC)	98.00 %
Solids content (weight-%):	2.0 %
· Other information	No further relevant information available.

10 Stability and reactivity

· Reactivity No further relevant information available.

• Thermal decomposition / conditions to be avoided: No decomposition if used according to specifications.

- · Possibility of hazardous reactions No dangerous reactions known.
- **Conditions to avoid** No further relevant information available.
- · Incompatible materials: No further relevant information available.
- · Hazardous decomposition products: Carbon monoxide

11 Toxicological information

· Information on toxicological effects

· Acute toxicity Based on available data, the classification criteria are not met.

· LD/LC50 values relevant for classification:

123-86-4 n-Butyl acetate

Oral LD50 13,100 mg/kg (rat)

Dermal LD50 >5,000 mg/kg (rabbit)

• Skin corrosion/irritation Based on available data, the classification criteria are not met.

- · Serious eye damage/irritation Causes serious eye irritation.
- Respiratory or skin sensitisation Based on available data, the classification criteria are not met.
- · Germ cell mutagenicity Based on available data, the classification criteria are not met.
- · Carcinogenicity Based on available data, the classification criteria are not met.

· Reproductive toxicity Based on available data, the classification criteria are not met.

- STOT-single exposure May cause drowsiness or dizziness.
- STOT-repeated exposure

May cause damage to the lung through prolonged or repeated exposure. Route of exposure: Inhalation.

(Contd. on page 6)

Printing date 28.09.2023

Safety Data Sheet

in accordance with HSNO

Version number 4

Revision: 22.09.2023

Trade name: Mipa 2K-Express-Beschleuniger

· Aspiration hazard Based on available data, the classification criteria are not met.

(Contd. of page 5)

12 Ecological information

- · Toxicity
- · Aquatic toxicity: No further relevant information available.
- · Persistence and degradability No further relevant information available.
- · Behaviour in environmental systems:
- · Bioaccumulative potential No further relevant information available.
- · Mobility in soil No further relevant information available.
- · Additional ecological information:
- · General notes:
- Water hazard class 1 (German Regulation) : slightly hazardous for water

Do not allow undiluted product or large quantities of it to reach ground water, water course or sewage system.

- · Results of PBT and vPvB assessment
- · PBT: Not applicable.
- · vPvB: Not applicable.

· Other adverse effects No further relevant information available.

13 Disposal considerations

- · Waste treatment methods
- · Recommendation

Must not be disposed together with household garbage. Do not allow product to reach sewage system.

- · Uncleaned packaging:
- · Recommendation:

Packagings that may not be cleansed are to be disposed of in the same manner as the product.

UN-Number	
NZS, IMDG, IATA	UN1263
UN proper shipping name	
NZŚ	UN1263 PAINT RELATED MATERIAL
IMDG, IATA	PAINT RELATED MATERIAL
Transport hazard class(es)	
NZS	
Class	3 (F1) Flammable liquids.
Label	3





Printing date 28.09.2023

Safety Data Sheet

in accordance with HSNO

Version number 4

Revision: 22.09.2023

Trade name: Mipa 2K-Express-Beschleuniger

	(Contd. of page
IMDG, IATA	
3	
Class	3 Flammable liquids.
Label	3
Packing group	
NZS, IMDG, IATA	11
Environmental hazards:	Not applicable.
Special precautions for user	Warning: Flammable liquids.
Hazard identification number (Kemler code):	
EMS Number:	F-E, <u>S-E</u>
Stowage Category	В
Transport in bulk according to Annex II of	
Marpol and the IBC Code	Not applicable.
Transport/Additional information:	
NZS	
Limited quantities (LQ)	5L
Transport category	2
Tunnel restriction code	D/E
IMDG	·
Limited quantities (LQ)	5L
UN "Model Regulation":	UN 1263 PAINT RELATED MATERIAL, 3, II

15 Regulatory information

· Safety, health and environmental regulations/legislation specific for the substance or mixture

· HSNO Approval numbers		
123-86-4	n-Butyl acetate	HSR001091
141-78-6	Ethyl acetate	HSR001041
CHS lobal alamanta		

GHS label elements

The product is classified and labelled according to the Globally Harmonised System (GHS).



GHS02 GHS07 GHS08

· Signal word Danger

 Hazard-determining components of labelling: n-Butyl acetate Benzoic acid Ethyl acetate
Hazard statements H225 Highly flammable liquid and vapour.

(Contd. on page 8)

NZ

Printing date 28.09.2023

Safety Data Sheet

in accordance with HSNO Version number 4

Revision: 22.09.2023

Trade name: Mipa 2K-Express-Beschleuniger

(Contd. of page 7) H319 Causes serious eye irritation. H336 May cause drowsiness or dizziness. H373 May cause damage to the lung through prolonged or repeated exposure. Route of exposure: Inhalation. · Precautionary statements P210 Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. P260 Do not breathe dust/fume/gas/mist/vapours/spray. P280 Wear protective gloves/protective clothing/eye protection/face protection/hearing protection. P303+P361+P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower]. P304+P340 IF INHALED: Remove person to fresh air and keep comfortable for breathing. P305+P351+P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. · Directive 2012/18/EU · Named dangerous substances - ANNEX I None of the ingredients is listed. Seveso category P5c FLAMMABLE LIQUIDS • Qualifying quantity (tonnes) for the application of lower-tier requirements 5,000 t • Qualifying quantity (tonnes) for the application of upper-tier requirements 50,000 t · National regulations: · Additional classification according to Decree on Hazardous Materials, Annex II: Class | Share in % NK 50-100 · Other regulations, limitations and prohibitive regulations Surface Coatings and Colourants (Flammable) Group Standard 2006 HSNO Approval Number: The HSNO Approval Number for this Group Standard is HSR002662. Refer also to the Site & Storage requirements document. · Chemical safety assessment: A Chemical Safety Assessment has not been carried out. 16 Other information This information is based on our present knowledge. However, this shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship. Relevant phrases H225 Highly flammable liquid and vapour. H226 Flammable liquid and vapour. H315 Causes skin irritation. H318 Causes serious eye damage. H319 Causes serious eye irritation. H336 May cause drowsiness or dizziness. H372 Causes damage to organs through prolonged or repeated exposure. · Contact: Abbreviations and acronyms: ADR: Accord relatif au transport international des marchandises dangereuses par route (European Agreement Concerning the International Carriage of Dangerous Goods by Road) IMDG: International Maritime Code for Dangerous Goods IATA: International Air Transport Association EINECS: European Inventory of Existing Commercial Chemical Substances ELINCS: European List of Notified Chemical Substances CAS: Chemical Abstracts Service (division of the American Chemical Society) VOC: Volatile Organic Compounds (USA, EU) LC50: Lethal concentration, 50 percent LD50: Lethal dose, 50 percent PBT: Persistent, Bioaccumulative and Toxic vPvB: very Persistent and very Bioaccumulative (Contd. on page 9)



Safety Data Sheet

in accordance with HSNO Version number 4

Revision: 22.09.2023

Printing date 28.09.2023

Trade name: Mipa 2K-Express-Beschleuniger

(Contd. of page 8)

Flam. Liq. 2: Flammable liquids – Category 2 Flam. Liq. 3: Flammable liquids – Category 3 Skin Irrit. 2: Skin corrosion/irritation – Category 2 Eye Dam. 1: Serious eye damage/eye irritation – Category 1 Eye Irrit. 2: Serious eye damage/eye irritation – Category 2 STOT SE 3: Specific target organ toxicity (single exposure) – Category 3 STOT RE 1: Specific target organ toxicity (repeated exposure) – Category 1 STOT RE 2: Specific target organ toxicity (repeated exposure) – Category 2 • * **Data compared to the previous version altered.**

NZ -